Qty:

Each

4 Um:

: STEP WELDMENT

: D2563

: N/A

: C

: D2563 REV C

: 25/07/2008

Date: User:

Wednesday, 25/06/2008 11:59:48 AM

Julie Lecocq

Process Sheet

Drawing Name

Part Number

Material

Due Date

Drawing Number

Project Number

Drawing Revision

Customer

: CU-DAR001 Dart Helicopters Services

Job Number

Estimate Number

: 40083A : 10176

P.O. Number

This Issue

: 25/06/2008

Prsht Rev. : NC

First Issue

Previous Run

: //

: 39867

S.O. No. :

Type : LARGE FAB ASSY

Written By Checked & Approved By

Comment

: Est Rev:G 02.07.31

Re-format Location RF

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0

D2244116

Step Extrusion

Comment: Qty.: 1.0000 Each(s)/Unit

Total: 4.0000 Each(s)

Pick:

D2244

Step Extrusion

Batch: __<

D267334

End Plate

2.0

2.0000 Each(s)/Unit

Total:

8.0000 Each(s)

Pick:

Comment: Qty.:

Qty Part No. Description

D2673-34

End Cap

08.09.315



3.0

D2561

2

Lug



Part No.


D2561

Comment: Qty.:

2.0000 Each(s)/Unit

Total:

8.0000 Each(s)





4.0

Lug Plate

Description

2 D2564

Pick:

Qty

Comment: Qty.:

2.0000 Each(s)/Unit

Total:

8.0000 Each(s)

Pick:

Qty Part No.

D2564

Description

Mounting Angle



Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES									
DATE STEP		PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
		·				·					
		, -									

Part No:	PAR #:	Fault Category:	NCR: Yes	No	DQA:	Date: _	
			QA: N	/C C	losed:	Date: _	

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
		Description of NC		Corrective Action Section B		Verification	Annewal	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector
		·	- proposed g		1			
						•	л -	
		٠,		÷				
				,				
		•						
1					1	İ		•

NOTE: Date & initial all entries

Date: Wednesday, 25/06/2008 11:59:48 AM User: Julie Lecoca **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services **Drawing Name: STEP WELDMENT** Job Number: 40083A Part Number: D2563 Job Number: Seq. #: Machine Or Operation: Description: LARGE FAB 1 LARGE FABRICATION RESOURCE 1 5.0 Comment: LARGE FABRICATION RESOURCE 1 1-Cut D2244 to 89.70" at 34 deg as per dwg D2563 2-Deburr ends 08/06/27 3-Weld (1 END CAP, LUG PLATES & MOUNTING ANGLE) as per dwg D2563 using DT 8343 A/R AL ROD Batch: 108350 SP 08.09.15 4- Grind VISUAL WELDING INSPECTION QC9 6.0 Comment: VISUAL WELDING INSPECTION INSPECT WORK TO CURRENT STEP 7.0 QC5 Comment: INSPECT WORK TO CURRENT STEP HAND FINISHING1 HAND FINISHING RESOURCE #1 Comment: HAND FINISHING RESOURCE #1 Chemical Conversion Coat as per QSI 005 4.1 INSPECT POWDER COAT/CHEMICAL CONVERSION 9.0 QC3 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION LARGE FAB 1 LARGE FABRICATION RESOURCE 1 10.0 Comment: LARGE FABRICATION RESOURCE 1 1-Inspect for foreign object per QSI 024 2-Weld Remainig End as per Dwg-D2563 using DT 8343 Batch: 108 AL ROD 9,5P08.09.16 3-Grind

Dart	Aeros	pace	Ltd
- u	70100		

	WORK ORDER CHANGES										
STEP	PROCEDURE CHANGE	PROCEDURE CHANGE By		Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector					
		·									
	STEP	STEP PROCEDURE CHANGE	STEP PROCEDURE CHANGE By	STEP PROCEDURE CHANGE By Date	STEP PROCEDURE CHANGE By Date Qty	STEP PROCEDURE CHANGE By Date Qty Chief Eng / Prod Mgr					

Part No:	<u> </u>	PAR #:	Fault Category:	NCR: Yes No DQA:	Date:
		7		QA: N/C Closed:	Date:

NCR:		WORK ORDER NON-CONFORMANCE (NCR)										
		Description of NC		Corrective Action Section B	· 	Verification	Annroyal					
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector				
		A Committee of the Comm										
	1	e de la companya de l		* .				-				
		·										

NOTE: Date & initial all entries

Date: Wednesday, 25/06/2008 11:59:48 AM User: Julie Lecocq **Process Sheet Drawing Name: STEP WELDMENT** Customer: CU-DAR001 Dart Helicopters Services Job Number: 40083A Part Number: D2563 Job Number: Seq. #: **Machine Or Operation:** Description: 11.0 QC9 VISUAL WELDING INSPECTION **Comment: VISUAL WELDING INSPECTION** 08-09-17 QC5 12.0 INSPECT WORK TO CURRENT STEP Comment: INSPECT WORK TO CURRENT STEP POWDER COATING 13.0 POWDER COATING M108523 Comment: POWDER COATING Touch up Alodine then Powder Coat White Gloss (Ref: 4.3.5.1) as per QSI 005 4.3 3:30pm 370°F START TIME: OVEN TEMPERATURE: 4:00pm FINISH TIME: 14.0 HAND FINISHING1 HAND FINISHING RESOURCE #1 188496 Comment: HAND FINISHING RESOURCE #1 Wing Walk as per Dwg D2563 and QSI 005 4.4 INSPECT POWDER COAT/CHEMICAL CONVERSI 15.0 QC3 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION FINAL INSPECTION/W/O RELEASE 16.0 QC21

Job Completion

Comment: FINAL



MF 08-09-20

Dart Aerospace Ltd

W/O:			· · · · · · · · · · · · · · · · · ·				
DATE STEP		PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			·		·		
							į.

Part No:	PAR #:	Fault Category:	NCR: Yes No	DQA:	Date:
			QA: N/C	Closed:	Date:

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC		Corrective A	ction Section I	3	Verification	Approval Chief Eng	Approval QC Inspector		
DATE	STEP	Section A	Initial Chief Eng	Action I	Description nief Eng	Sign & Date	Section C				
				:	ageth 2005						
					.						
					.*						
					,						

NOTE: Date & initial all entries

